



NOTES:

1. CLEANOUT FRAME AND COVER TO BE RETURNED TO THE ACSA.
2. ANY WORK TAKING PLACE ON ASBESTOS CEMENT PIPE IS TO BE PERFORMED BY CERTIFIED PERSONNEL.
3. SEE ACSA DETAIL S-10 FOR LATERALS ENTERING A MANHOLE.

**AUGUSTA COUNTY SERVICE AUTHORITY
VERONA, VIRGINIA**

SCALE: NTS

DRAWN BY: ACSA

DATE: APRIL 2021

REVISED:

SEWER SERVICE ABANDONMENT

DRAWING NUMBER: S-12

PAGE: 1 OF 1